


To guarantee accurate and repeatable machine accuracy, various other components in the total machining process need to be correctly and accurately positioned. The Center Height Gauge allows the spindle center and spindle orientation to be checked. In addition, the gauge can also be used for tool presetter verification.

Taper	Gauge Length	Diameter	fg	Order Number
Capto C3	lg=40	Dg=34	22	455.110.C03.000
Capto C4	lg=50	Dg=42	27	455.110.C04.000
Capto C5	lg=60	Dg=52	35	455.110.C05.000
Capto C6	lg=65	Dg=65	45	455.110.C06.000
Capto C8 and C8X	lg=80	Dg=82	55	455.110.C08.000
Capto C10	Contact us			455.110.C10.000

Preventive Maintenance Gauges

Dimensional Gauges, Balancing Masters, Coolant Supply Gauges, Center Height/Master Setting, Tool Changer Alignment Gauges, Machine Set-up Gauges. Also ask us about custom gauges and personalized solutions for your machine or machine tool.

Runout Test Arbors



Available for all major machine tapers, including CAT/DIN/BT Steep Taper, HSK, Capto, KM, Morse, and others.

Chuck Force Gauges



Measure chuck jaw clamping force at high speeds. Also available for other chuck measuring applications.

Drawbar Force Gauges



Measure tool clamping force to protect spindles and ensure machining accuracy.

Custom Machine Tool Gauges

Any gauge for any machine or machine tool.

