



Used for fitting onto machine spindle or in standard SK adapters for holding HSK tools.

Design

The adjusting screw on the machine spindle can be precisely set in radial run-out by using threaded pins (for alignment).

Includes

Clamping cartridge, stop/cover ring, and cylindrical holding screw (for holding KS adapter flange).

Note

On request the adapter flanges can be supplied with a KS clamping cartridge for use with minimal lubrication (MQL).

Available for HSK-C 32, 40, 50, 63, 80, 100