Rev. 12-1101 Page 1 of 1 Uncontrolled Document



The basic storage stand is designed for vertical storage of a runout arbor in a protected gauge closet, etc. (the taper is not protected). Stands are available upon request at no charge with runout arbor purchase. Stand is made of solid hardwood.

	Part Number
Runout Arbor Basic Storage Stand	465.003.000.000

Preventive Maintenance Gauges

Dimensional Gauges, Balancing Masters, Coolant Supply Gauges, Center Height/Master Setting, Tool Changer Alignment Gauges, Machine Set-up Gauges. Also ask us about custom gauges and personalized solutions for your machine or machine tool.



Available for all major machine tapers, including CAT/DIN/BT Steep Taper, HSK, Capto, KM, Morse, and others.

Chuck Force Gauges



Measure chuck jaw clamping force at high speeds. Also available for other chuck measuring applications.

Drawbar Force Gauges

Measure tool clamping force to protect spindles and ensure machining accuracy.







