

Used to clean lubricant and debris from inside the spindle to prevent slipping and poor face contact with the taper. Made with plastic and soft fiber pads for safe contact inside spindles. Recommended cleaning accessory before gauging and performing measurements inside the spindle.

Taper	Order Number
Steep Taper 30	530.100.830.000
Steep Taper 40	530.100.840.000
Steep Taper 45	530.100.845.000
Steep Taper 50	530.100.850.000
Steep Taper 60	530.100.860.000

**TAC Rockford Product Line**

Machine Tool Gauges, Tool Changer Alignment, Runout Test Arbors, Workholding Systems, Tool Holders, Adapters and Extensions, Tool Holder Blanks, Machine Tool Accessories, Coolant Tubes and Gauges, Heat Shrink Systems, Rapid Prototyping


**Tool Holders**



**Gauges**



**Accessories**



**Rapid Prototyping**

