





- Maximum runout error 0.005mm / 5 micron / 0.0002 inch. Contact us for availability on ultra-precision 0.001mm runout arbors.
- Carrying cases are not included. Visit www.tac.us/runoutcases for available case styles (Data Sheet 465.006).
- A certificate of accuracy is included.
- Contact us for other lengths, tapers, and other special requirements.

Taper	Length	Diameter	Part Number
KM32 Runout Arbor	70	32	465.K32.000.000
KM40 Runout Arbor	80	40	465.K40.000.001
KM50 Runout Arbor	Contact us		465.K50.000.001
KM63 Runout Arbor	340	50	465.K63.000.000
KM63 Runout Arbor	120	63	465.K63.000.001
KM6350 Runout Arbor	300	50	465.K65.000.000
KM80 Runout Arbor	350	50	465.K80.000.000
KM80 Runout Arbor	120	80	465.K80.000.001
KM100 Runout Arbor	340	50	465.K90.000.000
KM100 Runout Arbor	120	100	465.K90.000.001
KM10080 Runout Arbor	300	50	465.K98.000.000

Overview: Spindle Runout Arbor Carrying Cases (465.006)

Preventive Maintenance Gauges need to be transported on a frequent basis, or need to be stored in one area for a period of time, we can offer a reliable solution. Dimensional Gauges, Balancing Masters, Coolant Supply Gauges, Center Height Master Setting, Tool Changer Alignment Gauges, Machine Set-up Gauges. Also ask us about custom gauges and personalized solutions for your machine or machine tool.

Runout Test Arbors



Available for all major machine tapers, including CAT/DIN/BT Steep Taper, HSK, Capto, KM, Morse, and others.

Chuck Force Gauges



Measure chuck jaw clamping force at high speeds. Also available for other chuck measuring applications.

Drawbar Force Gauges



Measure tool clamping force to protect spindles and ensure machining accuracy.

Custom Machine Tool Gauges

Any gauge for any machine or machine tool.

